

**950N1-7208 NEOBE LIGHTBAR**  
0106 - FACTORY SET FLASH PATTERN

Switch application

**Mode 1**

+12 vdc **ORANGE** or (**ORG & WHT/BLK**) Control Wire Activated  
Front Warning Lamps: *Alternating without DF4 & PF4 - 6 pulse Neobe*  
Side & Corner Warning Lamps: *Side Only - 6 pulse Neobe*

**Mode 2**

+12 vdc **ORANGE & BLUE** or (**WHT/BLK**) Control Wires Activated  
Front Warning Lamps: *Alternating - 6 pulse Neobe*  
Side & Corner Warning Lamps: *All On - 6 pulse Neobe*

**Traffic Directional Modes**

Front Directional Lamps: *Left, Right or Center Out - 6 pulse Neobe*  
Side & Corner Warning Lamps: *Off*

**Any other combinations of the ORG, BLUE and WHITE/BLACK control wires = OFF.**

**See 950N1-7208 Appendix A for additional 950N1-7208 Control & Power Wire functions.**